

NOTICE TO MARINERS

Shoaling exists in the outlying areas of Santa Cruz Harbor and shallow conditions exist along the east and west jetties on both sides of the marked federal entrance channel.

Mariners transiting the harbor entrance should use caution and be aware of shallow conditions, especially during low tides and large surf. Mariners are also advised while underway in the Santa Cruz Harbor to navigate within the federal marked channel and stay between the marked main channel buoys.

All boaters are advised to check the most recent bathymetric sounding prior to transit. Boaters with deeper draft vessels are advised to be especially vigilant, particularly at lower tides and when operating along the east/west margins of the channel. The sounding is available on the Port District's website (www.santacruzharbor.org).

Santa Cruz Port District
May 26, 2017
(831) 475-6161