

ATTENTION BOATERS!

SHALLOW CONDITIONS AT THE HARBOR ENTRANCE

Shallow conditions exist in the entrance channel. The channel is narrowed by tip shoals that have formed at the ends of the jetties, particularly along the western side of the harbor mouth. Breaking surf is expected to occur during certain tide and swell conditions.

Prior to transiting the entrance, boaters are advised to check the harbor's website for the latest sounding, be knowledgeable about swell and tide conditions at the time of voyage and know their vessel's draft.

Harbor staff will continue to monitor entrance conditions and post updates to the sounding online. For the latest conditions, contact the harbor office.

Harbormaster
Santa Cruz Harbor
(831) 475-6161 VHF Ch. 9
Wednesday, December 19, 2018